1-00434	BD FUEL INJECT	8/17/2018			
Model	Full Credit Criteria	Deduction	No Credit		
P7100 Injection Pump	<ul> <li>Like for Like, application years &amp; models must match.</li> <li>No external damage</li> <li>All components present and assembled.</li> </ul>	<ul> <li>Governor Housing Damaged Front or Back (25% Deduction)</li> <li>Main Body Damaged (50% Deduction)</li> <li>AFC Housing Damaged (25% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> </ul>	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Damaged Camshaft on 911/913 pumps.</li> <li>Part disassembled</li> </ul>		
Bosch VE Pump	<ul> <li>Like for like</li> <li>No Fire Damage</li> <li>All components present and assembled.</li> <li>No external damage</li> </ul>	<ul> <li>Missing Parts (50% Deduction)</li> <li>AFC Housing Damaged (25% Deduction)</li> <li>Main Body Damaged (50% Deduction)</li> <li>Cold Advanced Housing Damaged (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Seized Head (Does not turn)</li> <li>Part disassembled</li> </ul>		
CP3	<ul> <li>Like for Like</li> <li>No Housing Damage</li> <li>All components present and assembled.</li> </ul>	Missing/Damaged Metering Unit (50% Deduction)	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Seized (Does not turn)</li> <li>Part disassembled</li> </ul>		
High Performance CP3	<ul> <li>No Housing Damage</li> <li>All components present and assembled.</li> </ul>	Missing Metering Unit (50% Deduction)	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Seized (Does not turn)</li> <li>Part disassembled</li> </ul>		
VP44	<ul> <li>All components present and assembled.</li> <li>Like for like models</li> <li>Must be rebuildable</li> </ul>	<ul> <li>Missing or Damaged Electronics (50% Deduction)</li> <li>Seized Head (Does not turn) (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Damaged Housing</li> <li>Part disassembled</li> </ul>		
High Performance VP44	<ul><li>All components present and assembled.</li><li>Must be rebuildable</li></ul>	<ul> <li>Missing or Damaged Electronics (50% Deduction)</li> <li>Seized Head (Does not turn) (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Damaged Housing</li> <li>Part disassembled</li> </ul>		
Common Rail Injectors	<ul> <li>All components present and assembled.</li> <li>Like for like models</li> <li>Body and threads are in good quality</li> <li>Solenoid Broken plastic tabs allowed.</li> </ul>		<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Damaged Body</li> <li>Part disassembled</li> <li>Solenoid melted or destroyed</li> </ul>		
Mechanical Injectors	Like for like     Body and threads are in good quality		<ul> <li>Fire Damage</li> <li>Contaminated/Bio Diesel</li> <li>Excessive Rust or water damage</li> <li>Damaged Body</li> <li>Part disassembled</li> </ul>		
Freight and Removal damage are not covered. Ensure you packaged the core sufficiently!					

1-00434	BD TURBOCHARGER	CORE ACCEPTANCE POLICY	
Turbo Model/ Application	Full Credit Criteria	Deduction	No Credit
Cummins ISX VGT Air or Electronic Actuated	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Damaged Electronics (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Heavily damage wheels and/or shaft (50% Deduction)</li> <li>Turbine Wheel Separation (50% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water damage</li> </ul>
Caterpillar (Ball Bearing) Models	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models, must have CAT logo</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Heavily damage wheels and/or shaft (50% Deduction)</li> <li>Turbine Wheel Separation (50% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water damage</li> </ul>
Caterpillar (Standard Turbocharger) 704604-9007, 704604-9011)	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like, must have CAT or Garrett logo. 4 Support Webs</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Heavily damage wheels and/or shaft (50% Deduction)</li> <li>Turbine Wheel Separation (50% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water damage</li> <li>Turbo with 3 support Webs</li> </ul>
Detroit Diesel VGT	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Heavily damage wheels and/or shaft (50% Deduction)</li> <li>Turbine Wheel Separation (50% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water</li> </ul>

Ford 6.4 Powerstroke	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Damaged VGT cage due to turbine wheel explosion (50%)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water</li> </ul>		
Dodge Cummins 6.7 HE351VG/HE300VG	<ul> <li>Light or minimal damaged to Compressor &amp; Turbine Wheel.</li> <li>Light or minimal damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water</li> </ul>		
Standard Turbochargers (All Models, Non VGT)	<ul> <li>On Vehicle damaged to Compressor &amp; Turbine Wheel.</li> <li>On Vehicle damage to compressor and turbine housing.</li> <li>All components present and assembled.</li> <li>Like for like models</li> </ul>	<ul> <li>Missing Parts or Actuators (50% Deduction)</li> <li>Damaged Electronics (50% Deduction)</li> <li>Missing Clamps (25% Deduction)</li> <li>Cracked or Damaged due to freight (50-100%)</li> <li>Damaged Electronics (50% Deduction)</li> </ul>	<ul> <li>Fire Damage</li> <li>Knock Off Models (Not Genuine)</li> <li>Excessive Rust or water</li> </ul>		
Freight and Removal damage are not covered. Ensure you packaged the core sufficiently!					

	BD TRANSMISSION ACCE		
Model	Full Credit Criteria	Deduction	No Credit
Transmissions	<ul> <li>No external damage</li> <li>No case cracks</li> <li>Drive shafts intact</li> <li>Dowel pin holes not damaged</li> <li>Threads not damaged</li> <li>No missing pieces</li> <li>Like for Like</li> <li>Must be assembled</li> </ul>	<ul> <li>Cracked or heavily corroded extension/OD housings</li> <li>Broken shafts (Requires disassembly for accurate costing)</li> <li>Missing electronics</li> </ul>	<ul> <li>Catastrophic damaged</li> <li>Damaged input shaft area, destroyed pump, case and convertor area</li> <li>Cracked Case</li> <li>Fire</li> <li>Excessive corrosion</li> </ul>
Torque Convertors	<ul> <li>No Rust</li> <li>No damage to Hub, Impeller and turbine</li> <li>Like for like</li> </ul>	<ul> <li>Hub and Impeller undamaged.</li> <li>Modified/Aftermarket convertors in which the stator or turbine have been modified. (Only on purchased cores)</li> </ul>	<ul><li>Excessive corrosion</li><li>Seized</li><li>Catastrophic failure</li></ul>
Valve Bodies	<ul><li>Like for like</li><li>No missing parts</li></ul>	Missing electronics	Excessive corrosion

# **GENERAL CORE ACCEPTANCE POLICY**

Freight and removal damage are not covered. Ensure you packaged the core sufficiently!

# Core must be rebuildable!